


















# AM 2011B

① Base  X1	② GasColumn  X1	④ Armrest  X2	<b>A</b> 	<b>B</b> 	<b>C</b> 
X5 	③ Three cups  X1	⑤ Mechanism  X1			










  

SCREWS LIST			
A	M6x20mm		x4
B	M6x25mm		x8
C	M8x16mm		x3
D	M6xR16		x4
E	M5		






  

<b>D</b> 	<b>E</b> 	<b>F</b> 
---	---	--




# AM 2011B

① Base  X1	② GasColumn  X1	④ Armrest  X2	<b>A</b> 	<b>B</b> 	<b>C</b> 
X5 	③ Three cups  X1	⑤ Mechanism  X1			

SCREWS LIST			
A	M6x20mm		x4
B	M6x25mm		x8
C	M8x16mm		x3
D	M6xR16		x4
E	M5		

<b>D</b> 	<b>E</b> 	<b>F</b> 
---	--	---