









PARTS LIST



HARDWARE LIST


NO.	Drawing	Description	Qty	PCS SET	NO.	Drawing	Description	Qty	PCS SET
A		∅15x9	8	PCS	G		M6x30	4	PCS
B		∅7x35	8	PCS	H		4MM	1	PCS
C		∅6x30	8	PCS	I		M6x25	10	PCS
D		∅4x40	8	PCS	J			4	PCS
E		∅3.5x16	24	PCS	K		120x40x17	2	PCS
F		∅3.5x12	32	PCS	L		∅5x (10+10)	4	PCS

1 ATTENTION

During assembly, first loosely align all screws with the corresponding pre-drilled holes and then tighten the screws one by one.

STEP 1


B x8pcs



STEP 2


A x8pcs

C x4pcs




STEP 3

C x4pcs
D x8pcs



STEP 4


E x24pcs
F x4pcs



3


STEP 5

G x4pcs
H x1pcs




STEP 6

I x10pcs




STEP 7

F x8pcs
J x4pcs



STEP 8


F x20pcs
K x2pcs



5

STEP 9

L x4pcs



STEP 10

