












PARTS LIST



HARDWARE LIST


NO.	Drawing	Description	Qty	PCS SET	NO.	Drawing	Description	Qty	PCS SET
A		∅ 15x9	12	PCS	K		∅ 3x12	4	PCS
B		∅ 7x35	12	PCS	L		108x25x9MM	4	PCS
C		∅ 6x30	10	PCS	M		M4x20	8	SET
D		∅ 3.5x14	4	PCS	N			4	PCS
E			2	SET	O			4	PCS
F		∅ 4x40	10	PCS	P		∅ 3.5x16	28	PCS
G		∅ 35x190	4	PCS	Q		180x20x3	2	PCS
H		4MM	1	PCS	R			4	PCS
I		M6x20	8	PCS	S		∅ 7.8x38	2	PCS
J			4	PCS					

1 ATTENTION

During assembly, first loosely align all screws with the corresponding pre-drilled holes and then tighten the screws one by one.


STEP 1

B x8pcs
D x4pcs
E₁ x2pcs




STEP 2

B x4pcs




STEP 3

A x4pcs
C x2pcs




STEP 4

C x2pcs
F x4pcs




STEP 5

A x8pcs
C x4pcs




STEP 6

C x2pcs
F x4pcs




STEP 7

G x4pcs
H x1pc
I x8pcs




STEP 8

J x4pcs




STEP 9

E₂ x4pcs
 K x4pcs
 L x4pcs
 M x8pcs




STEP 10

N x4pcs
 O x4pcs



STEP 11

P x22pcs




STEP 12

P x6pcs


Q x2pcs

R x4pcs



STEP 13

F x2pcs
S x2pcs



STEP 14

