








PARTS LIST



HARDWARE LIST


NO.	Drawing	Description	Qty	PCS SET	NO.	Drawing	Description	Qty	PCS SET
A		ø 15x9	28	PCS	J			2	PCS
B		ø 7x38	2	PCS	K		M3. 5x12	14	PCS
C		ø 7x35	28	PCS	L			4	PCS
D		ø 6x30	8	PCS	M			4	PCS
E			2	PCS	N			4	PCS
F			2	PCS	O		ø 3. 5X16	22	PCS
G	 @	M4x20	4	PCS	P			2	PCS
H			2	PCS	Q		ø 4	2	PCS
I		ø 4x40	10	SET					

1 ATTENTION

During assembly, first loosely align all screws with the corresponding pre-drilled holes and then tighten the screws one by one.


STEP 1

- A x2pcs
- C x6pcs
- K x2pcs
- M x4pcs
- P x2pcs
- Q x2pcs




STEP 2

- A x2pcs
- C x2pcs
- J1 x2pcs
- K x4pcs




STEP 3

A x8pcs
C x8pcs




STEP 4

A x8pcs
C x4pcs
D x8pcs



STEP 5

L x4pcs




STEP 6

B x8pcs


C x8pcs

I x8pcs




STEP 7

G x4pcs
H x2pcs
J2 x2pcs
K x4pcs




STEP 8

N x4pcs




STEP 9

E x2pcs
F x2pcs



STEP 10

0 x22pcs



STEP 11

B x2pcs
I x2pcs

