ASSEMBLY INSTRUCTION

-Description: RoppingChair

Hardware List:

A x 4 Pcs
Bolt M6x 40

B x 4 Pcs
CapNut M6x13

Z x 2 Pcs
Allen key M4

X2 Pcs

X1 Pc

Step I

Step II

FINISHED