ASSEMBLY INSTRUCTION

Step 1

A

B

Step 2

The lights (C) were strung round the tree.

HARDWARE LIST		
CODE	PARTS	QTY.
A		1PC
B		1PC
C		1PC