







X3

O 01 02 03 04 2PCS	H 12PCS	A 24PCS
P 7*50 6PCS	I 400mm I2 I1 3PCS	B 24PCS
	J 3.5*30 12PCS	C 8*40 12PCS
	K 10PCS	D 64PCS
	L 3*12 10PCS	E 64PCS
	M 3.5*14 30PCS	F 6*30 18PCS
	N 3.5*12 12PCS	G 3PCS

1



985*585 1PS

2



985*585 1PS

3



400*585 1PS

4



366*429 3PS

5



400*585 1PS

6



368*60 1PS

7



368*80 1PS

8



368*80 1PS

9



368*60 3PS

10

994*378 1PS

11



714*378 1PS

12



400*120 3PS

13



400*120 3PS

14



318*120 3PS

15



326*396 3PS

16



394*205 3PS

17



1018*394 1PS

18



883*130 1PS

19



883*130 1PS

20



277*60 1PS

21



277*60 4PS

22



277*117 4PS

23



785*585 1PS

24



785*585 1PS

















	A*24	put A on board (1)(2)(3)(5)(23)(24)
	C*12	put C on board (1)(2)(23)(24)
	D*12	put D on board (23)(24)

2















	F*18	put F on board (18)(19)(20)(21)(22)
	D*52	put D on board (16)(17)(18)(19)(21)

3





	B*8
	E*12

put B on board (7)(8)

put E on board (9)

4







Make sure the arrow on the screw
align to the hole on the side.







	B*4
	P*6

put B on board (6)

put P on board (5)

5

Make sure the arrow on the screw
align to the hole on the side.









	B*6	put B on board (1)(2)

6







Make sure the arrow on the screw align to the hole on the side.

	B*6

put B on board 23 24

7



X4



Make sure the arrow on the screw
align to the hole on the side.



	E*34	put E on board 20 21 22

8



Make sure the arrow on the screw align to the hole on the side.





	E*6	put E on board 18 19
	G*3	put G on board 17
	M*6	put M on board 17





X3





X3

	J*12	put J on board 12 13

10







Make sure the arrow on the screw align to the hole on the side.





	E*12
	N*12
	I2*6

put E on board 12 13

put N on board 12 13

put I2 on board 12 13

11





	M*12
	I1*6

put M on board 23 24

put I1 on board 23 24

12



	H*12

put H on board 1 2

13



17



2

1

	M*12	put M on board (1)

14



	K*10	put K on board 10 11
	L*10	put L on board 10 11

15









01 03 02 04	0*2