


ITEM#: 244 - B650124

## **DESCRIPTION: COUNTER HEIGHT CHAIR**

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have come loose inside the carton during shipment. Identify and count all parts and compare with the parts List Below:

### PART LIST:






STEP 2


### NOTE:


- 1. REMOVE LEGS FROM INNER BOX
- 2. DO NOT FULLY TIGHTEN SCREW, BOLTS UNTIL ALL PARTS COMPLETE ASSEMBLY.


	I			
NO.	Drawing	Description	Q'ty	
Α	0	Bolt (Φ5/16"×3-1/4")	4pcs	
В	<b>9</b>	Bolt (Φ5/16"×2-1/2")	4pcs	
С	<b>©</b>	Bolt (Φ5/16"×1-3/4")	1pc	
D	0	Flat washer (Ø5/16"x19mm)	9pcs	
Е	0	Spring washer (Ø5/16")	9pcs	
F		Allen wrench (5mm)	1pc	
G	(mmm>	Wood screw (Φ8x1-1/2")	6pcs	

HARDWARE LIST









# **CLEANING INSTRUCTION**


Clean the Counter Height Chair surface with a furniture polish and a soft cloth. Made in VietNam




ITEM#: 244 - GT3660

## **DESCRIPTION: GATHERING TABLE**

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts which may have come loose inside the carton during shipment. Identify and count all parts and compare with the parts List Below:








1. REMOVE SIDE FRAME FROM INNER BOX


2. DO NOT FULLY TIGHTEN SCREW, BOLTS UNTIL ALL PARTS COMPLETE ASSEMBLY.

HARDWARE LIST				
NO.	Drawing	Description	Q'ty	
Α	<b>~</b>	Bolt (Φ5/16"×1-3/4")	16pcs	
В	0	Flat washer (Ø5/16"x23mm)	16pcs	
С	0	Spring washer (Ø5/16")	16pcs	
D		Allen wrench (5mm)	1pc	









# **CLEANING INSTRUCTION**

Clean the Gathering Table surface with a furniture polish and a soft cloth.

Made in VietNam