



COUNTER TABLE ASSEMBLY INSTRUCTIONS


A. TABLE TOP 1PC




B. EXTENSION 1PC



C. LEGS 2PCS




D. CROSSBAR 1PC




E. RAIL LEFT 1PC





TABLE ASSEMBLED



F. RAIL RIGHT 1PC




HARDWARE ENCLOSED IN BOX

1	ALLEN BOLT M8 x 40 MM	02 PCS	2	ALLEN BOLT M8 x 50 MM	14 PCS	3	ALLEN BOLT M8 x 60 MM	02 PCS	4	THREAD BOLT M8 x 45 MM	01 PC	5	WASHER M9/22	16 PCS
														
6	SPRING WASHER M9/11	16 PCS	7	NUT M8	02 PCS	8	HALF MOON WASHER	02 PCS	9	SPANNER N13	01 PC	10	HEXAGON NUT M8	01 PC
														
11	WASHER M9/22	02 PCS	TOOL REQUIRED PHILLIPS HEAD SCREW DRIVER NOT PROVIDED 											
														


STEP 1:

FASTEN THE RAILS (E),(F) WITH THREAD BOLT (4) WASHERS (11), AND NUTS (7).




STEP 2:

ATTACH THE "X" BRACE TO THE TABLE TOP (A), FASTEN WITH BOLTS (2), WASHERS (5),(6).




STEP 3:

INSERT THE LEG (C) TO THE TOP BOTTOM SIDE OF THE TABLE (A). FASTEN THE LEG (C) WITH BOLTS (2), WASHERS (5),(6).





STEP 4:

INSERT THE CROSS BAR (D) TO "X" BRACE. FASTEN THE OTHER LEG (C) TO THE TABLE, WITH BOLTS (2), (3) WASHERS (5),(6) AND HALF MOON WASHER (8).






STEP 5:

**FASTEN THE CROSS BAR (D) WITH BOLTS (1), WASHERS (5),
SPRING WASHERS (6).**



STEP 6:


**TO ADD EXTENSION LEAF, SEPARATE TABLE HALVES BY
UN COUPLING, BRACKETS ON UNDERSIDE OF TABLE AND
PULL APART.**



UNLOCK



STEP 7:

ATTACH EXTENSION (B) TO THE TABLE TOP (A).



STEP 8:

PUSH TABLE HALVES BACK TOGETHER AND RECOUPLE BRACKETS ON UNDERSIDE OF TABLE.



LOCK

ASSEMBLY COMPLETE.