


Flathead machine screws+Gasket



Installation instruction




DT0113AW16/18 Installation The number of people needed for installation: 2

- ① Please read the manual carefully before installing this product.
  And strictly follow the installation process
- ② Please take good care of this manual for your next installation


## Parts list

Serial number	Shape	Name	Quantity
A		Flathead machine screws (M8*16)	12
В	0	Gasket	4
С		Steel plate	1


1. Place the support frame on the top of the base and align the interconnected holes, put in the hexagonal machine wire and gasket, and tighten it with a wrench.



2. Place the desktop on the top of the support frame and align the ears of the support frame with the holes of the bottom plate of the desktop, put in the hexagonal machine wire and gasket and tighten it with a wrench




3. Installation complete





Installation instruction



DT0113AW20 Installation
The number of people needed for
installation: 2

- Please read the manual carefully before installing this product. And strictly follow the installation process
- ② Please take good care of this manual for your next installation

Parts list

Serial number	Shape	Name	Quantity
A		Hexagon socket machine screws (M8*30)	8
В		Hexagon socket machine screws (M8*16)	4
С	0	Gasket	12