


# Assembly Instruction





## Important Note

### HARDWARE NOTE :


1. Two or more people are required for assembly
2. Do not screw on the bolts too tight unless the installation is done. Make sure all bolts are tightly screwed before you use it.

## Components






2





Please note the orientation of this hole



Please note the orientation of this hole



|   |                       |      |
|---|-----------------------|------|
| J |                       | 8pcs |
|   | $\phi 11.5 \times 10$ |      |

3





|   |                       |      |
|---|-----------------------|------|
| J |                       | 6pcs |
|   | $\phi 11.5 \times 10$ |      |

4




|   |                    |       |
|---|--------------------|-------|
| E |                    | 4pcs  |
|   | M8x50              |       |
| K |                    | 14pcs |
|   | $\phi 8 \times 40$ |       |

5




|   |                    |       |
|---|--------------------|-------|
| I |                    | 14pcs |
|   | $\phi 7 \times 40$ |       |


6




7




8



9




10




|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| J |  | 2pcs |
|   | $\phi 11.5 \times 10$                                                               |      |

11




|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| I |   | 8pcs |
|   | $\phi 7 \times 40$                                                                  |      |
| K |  | 4pcs |
|   | $\phi 8 \times 40$                                                                  |      |

12



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| J |  | 4pcs |
|   | $\phi 11.5 \times 10$                                                               |      |


13



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| K |  | 8pcs |
|   | $\phi 8 \times 40$                                                                  |      |
| J |  | 8pcs |
|   | $\phi 11.5 \times 10$                                                               |      |


Pass the LED  
stripconnector  
through the hole

# 14




|   |                                                                                     |       |
|---|-------------------------------------------------------------------------------------|-------|
| K |  | 10pcs |
|   | φ 8x40                                                                              |       |

# 15




|   |                                                                                      |       |
|---|--------------------------------------------------------------------------------------|-------|
| A |  | 16pcs |
|   | M8x12                                                                                |       |

# 16



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| A |  | 2pcs |
|   | M8x12                                                                               |      |


# 17 x2



|   |                                                                                      |       |
|---|--------------------------------------------------------------------------------------|-------|
| A |  | 16pcs |
|   | M8x12                                                                                |       |


18

x2



|   |                                                                                     |       |
|---|-------------------------------------------------------------------------------------|-------|
| D |  | 16pcs |
|   | M8x33                                                                               |       |


19



|   |                                                                                      |      |
|---|--------------------------------------------------------------------------------------|------|
| B |  | 4pcs |
|   | M8x20                                                                                |      |


Tighten screws C

20

Install screws loosely,  
don't fully tighten

|   |                                                                                     |      |            |
|---|-------------------------------------------------------------------------------------|------|------------|
| C |  | 4pcs | white zinc |
|   | M8x25                                                                               |      |            |

21




Tighten screws F

Install screws loosely,  
don't fully tighten

|   |                                                                                     |      |  |
|---|-------------------------------------------------------------------------------------|------|--|
| F |  | 4pcs |  |
|   | M8x60                                                                               |      |  |




22



|       |                                                                                     |      |
|-------|-------------------------------------------------------------------------------------|------|
| Q     |  | 4pcs |
| M8x40 |                                                                                     |      |

Assemble second

23




|       |                                                                                      |      |
|-------|--------------------------------------------------------------------------------------|------|
| B     |    | 2pcs |
| M8x20 |                                                                                      |      |
| 0     |  | 2pcs |
| M8x14 |                                                                                      |      |

white zinc



to Assemble first

24




|       |                                                                                     |      |
|-------|-------------------------------------------------------------------------------------|------|
| Q     |  | 3pcs |
| M8x40 |                                                                                     |      |

25







Note: Now you can tighten all the bolts.