











S2115K






Assembly Instruction




PARTS LIST

1 	2 		
1	1		
3 	4 		
1	1		
5 	6 	7 	8 
125mm=2	140mm=4	190mm=2	1
9 			
170mm=1			


HARDWARE LIST

A	B	C	D	E
				
M8*30=2	M8=2	M8=20	M8*30=17	M8*40=4
F				
				
4*30=4	M6=1			
			 phillips head screw driver required for assemble—not include	


Step 1




Step 2




Step 3




Step 3




Step 5



Step 6



Step 7



Step 8

