




Assembly Instruction





A=1PC



B=1PC



C=1PC




D=1PC




E=1PC




F=2PCS




G=2PCS




H=2PC





I=1PC



J=1PC



K=2PC



1	x12
M8*18mm	


2	x6
M8*35mm	

3	x5
M8*40mm	

4	x2
M8*65mm	


5	x1
5#	

1




2	x6	5	x1
M8*35mm		5#	

2





1	x4	5	x1
M8*18mm		5#	

3





4




3	x2	5	x1
			
M8*40mm		5#	

5




1	x8	3	x3	5	x1
					
M8*18mm		M8*40mm		5#	

6



4	x2	5	x1
			
M8*65mm		5#	

7



8

