



MAGNUSSEN[®]
H O M E
Bringing dreams home.

ASSEMBLY INSTRUCTIONS

CAUTION: PLEASE READ ALL INSTRUCTIONS BEFORE STARTING THE ASSEMBLY OF THIS PRODUCT.
THESE PIECES ARE HEAVY.

IN ORDER TO PREVENT PERSONAL INJURY AND ENSURE THAT THIS PRODUCT IS NOT
DAMAGED DURING THE ASSEMBLY PROCESS. IT IS STRONGLY RECOMMENDED THAT YOU
ENLIST THE ASSISTANCE OF ONE OR MORE PEOPLE.
IN CASE OF EXCESS STAIN, WIPE THE BOTTOM OF THE UNIT BEFORE PLACING ON ANY
SURFACE.

ATTENTION: VEUILLEZ LIRE TOUTES LES INSTRUCTIONS AVANT DE COMMENCER L'ASSEMBLAGE DE CE
PRODUIT. LES PIECES SONT LOURDES. POUR EVITER TOUTE BLESSURE ET POUR VOUS
ASSURER QUE LE PRODUIT N'EST PAS ENDOMMAGE' PENDANT
L'ASSEMBLAGE, NOUS VOUS RECOMMANDONS DE FAIRE APPEL A UNE OU PLUSIEURS
AUTRES PERSONNES.
EN CAS DE TACHE EXCESSIVE, ESSUYEZ LE FOND DE L'UNITÉ AVANT LE PLACEMENT SUR
N'IMPORTE QUELLE SURFACE.

CUIDADO: FAVOR DE LEER TODAS LAS INSTRUCCIONES ANTES DE ENSAMBLAR SU PRODUCTO, ESTAS
PIEZAS SON PESADAS.
PARA PREVENIR HERIDAS PERSONALES Y ASEGURAR QUE SU PRODUCTO NO SEA DAÑADO
MIENTRAS ES ENSAMBLADO. SE RECOMIENDA LA ASISTENCIA DE UNA O MÁS PERSONAS.

WARNING.....PROTECTIVE GLIDE IS PLACED UNDER LEGS OF FURNITURE TO RESIST SCRATCHES TO
FLOOR SURFACE. SOME FLOOR SURFACES CAN BE EXTRA SENSITIVE TO MARKING, IF YOU ARE NOT SURE
CONSULT WITH YOUR DEALER.

AVERTISSEMENT...LES PIEDS DES MEUBLES SONT MUNIS DE PATINS DESTINÉS À PROTÉGER LE PLANCHER.
CERTAINS REVÊTEMENTS DE SOL PEUVENT ÊTRE TRÈS FRAGILES. EN CAS DE DOUTE. CONSULTER LE
MARCHAND.




MAGNUSSEN[®]
H O M E
Bringing dreams home.


ASSEMBLY INSTRUCTIONS

MODEL:T2214-05



Step 1



Step 2



Step 3




T2214-05

LIST OF PARTS AND ARDWARE:

No.	Description	Q'ty
A	Bolt Ø1/4"*5/8"	6 PCS
B	Bolt Ø1/4"*1-3/4"	3 PCS
C	Lock Washer Ø1/4"	9 PCS
D	Flat Washer Ø1/4" *16	9 PCS
E	Allen Wrench 4mm	1 PC
F	Glass Bumper	3 PCS

LIST OF PARTS AND ARDWARE:

LIST OF PARTS AND ARDWARE:				
No.	Description			Q'ty
1	Top	PT2214-05 FR		1 PC
2	Leg	PT2214-05 LG		3 PCS
3	Shelf	PT2214-05 SH		1 PC
4	Foot	PT2214-05 FT		4 PCS
5	Glass	PT2214-05 GA		1 PC



MODEL:T2214-35

Step 1

Step 2

Step 3



The diagram illustrates the assembly of a K/D foot box. It is divided into three steps:

- Step 1:** A threaded rod (2) is shown with a washer (1) and a foot box (3) being prepared.
- Step 2:** The foot box (3) is placed on the rod (2) and secured with a nut (4) and a washer (4).
- Step 3:** The final assembly is shown with the foot box (3) and a K/D foot box (K/D foot box) being attached to the rod (2).

A technical diagram showing a bolt assembly. At the top, a circular flange with multiple raised bolts is shown with a curved arrow indicating rotation. A label '1' with a leader line points to this flange. Below it, a large downward-pointing arrow indicates the direction of assembly. In the center, a bolt with a hexagonal head is shown. A label '2' with a leader line points to the threaded shaft of the bolt. At the bottom, a circular base plate is shown. A label '3' with a leader line points to this base plate. The letter 'X' is positioned to the left of the bolt.

The diagram illustrates a mechanical assembly. At the top is a circular plate with two parallel lines in its center. A downward-pointing arrow is to its left. Below this plate is a ring-like component with 12 pins or bolts around its circumference. One pin is labeled 'E'. This ring is mounted on a threaded rod that passes through a base plate. The entire assembly is shown in a perspective view.

LIST OF PARTS AND ARDWARE:			
No.	Description		Q'ty
A	Bolt Ø1/4"*1-3/4"		2 PCS
B	Lock Washer Ø1/4"		2 PCS
C	Flat Washer Ø1/4" *16		2 PCS
D	Allen Wrench 1/4"		1 PC
F	Glass Bumper		3 PCS



LIST OF PARTS AND ARDWARE:				
No.	Description			Q'ty
1	Top			1 PC
2	Post	PT2214-35 PO		1 PC
3	Shelf	PT2214-35 SH		1 PC
4	Foot	PT2214-35 FT		4 PCS
5	Glass	PT2214-35 GA		1 PC



MAGNUSSSEN[®]
H O M E
Bringing dreams home.

ASSEMBLY INSTRUCTIONS

MODEL:T2214-37



T2214-37

LIST OF PARTS AND ARDWARE:

No.	Description	Q'ty
A	Glass Bumper	4 PCS

LIST OF PARTS AND ARDWARE:

No.	Description			Q'ty
1				1 PC
2	Small Glass Shelf	PT2214-37 GS1		1 PC
3	Middle Glass Shelf	PT2214-37 GS2		1 PC
4	Large Glass Shelf	PT2214-37 GS3		1 PC





MAGNUSSEN[®]
H O M E
Bringing dreams home.

ASSEMBLY INSTRUCTIONS

MODEL:T2214-47

Step 1



T2214-47

LIST OF PARTS AND ARDWARE:

No.	Description	Q'ty
A	Glass Bumper	8 PCS

LIST OF PARTS AND ARDWARE:

No.	Description			Q'ty
1				1 PC
2	Glass	PT2214-47 GA		1 PC




MAGNUSSSEN[®]
H O M E
Bringing dreams home.


ASSEMBLY INSTRUCTIONS

MODEL:T2214-75



Step 1



Step 2



Step 3



T2214-75

LIST OF PARTS AND ARDWARE:

No.	Description		Q'ty
A	Bolt Ø1/4"×5/8"		8 PCS
B	Bolt Ø1/4"×1-3/4"		4 PCS
C	Lock Washer Ø1/4"		12 PCS
D	Flat Washer Ø1/4" *16		12 PCS
E	Allen Wrench 4mm		1 PC
F	Glass Bumper		4 PCS

LIST OF PARTS AND ARDWARE:

No.	Description			Q'ty
1	Top	PT2214-75 FR		1 PC
2	Front Leg	PT2214-75 LG1		2 PCS
3	Back Leg	PT2214-75 LG2		2 PCS
4	Shelf	PT2214-75 SH		1 PC
5	Foot	PT2214-75 FT		4 PCS
6	Glass	PT2214-75 GA		1 PC