Installation Instructions

Wiring Pendant


Packing list:



Canopy Screw 2 Pcs



Cable Connector 2 PCS (LASDOP)



Mounting 1 Pcs Bracket

Additional Part Must be provided by customer:



Bracket 2 Pcs Box Screw



Screws Plug Fischer S6


CAUTION:

Tools Required: Phillips head screwdriver or screw bit



WARNING:

Turn off power at circuit before wiring and always consult a licensed electrician.



Assembly Steps:


(Lasdop)


- 1.Turn off power circuit And Tie overhand knot inside the Canopy.
- 2.Set the position of the lamp installation and then install crossbar (mounting bracket) first.
- 3.Connect Ground Cable to crossbar (mounting bracket).
- 4.Adjust the height of the chandelier and then Install the wire rope on the crossbar to hold the height of the pendant light.
- 5. Attach the positive wire to the positive wire and Negative wire to negative wire.
- 6.Connect matching cable with cable connectors and wrap secure with electrical tape.

Step 02

How to arrange hanging cables and wires:

CAUTION: For safety during installation, Assembly must be carried out by two people.





1.Adjust the height of the chandelier cable.

5. Arrange the cables neatly before installing the canopy.

- 2.Adjust the length of the light cable.
- 3.Before locking the cable, for cable safety so as not to break during installation. Adjust the slightly loosened wire from the chandelier wire rope.
- 4. After that lock the cable at the bottom of the canopy by turning it tightly.

6. Attach the canopy to the mounting Bracket that has been installed on the ceiling then bolt on the side of the canopy.