





| NO.  | LINEDRAWING |
|------|-------------|
| A×18 |             |
| B×18 |             |
| C×16 |             |
| D×12 |             |
| E×6  |             |
| F×56 |             |
| G×2  |             |
| H×4  |             |
| I×2  |             |
| J×4  |             |



| NO. | QTY. |
|-----|------|
| ①   | 1    |
| ②   | 1    |
| ③   | 1    |
| ④   | 2    |
| ⑤   | 1    |
| ⑥   | 3    |
| ⑦   | 1    |
| ⑧   | 1    |
|     |      |
|     |      |

1

|       |             |
|-------|-------------|
| <br>A | <br>C       |
| 18x   | 8x40<br>16x |

2





|       |
|-------|
| <br>B |
| 6x    |

3



4

3 of 6

|       |
|-------|
| <br>B |
| 6x    |




9




6x

10

F  
4\*14mm  
12xD  
12x

11








2x



4x



F  
3.5x14  
12x

12

F  
3.5x14  
16x

5 of 6

13



I  
2x