


INSTALLATION INSTRUCTIONS


NO.HKBFDC049

ASSEMBLY DIAGRAM



PARTS LIST


No.	Description	QTY	No.	Description	QTY	No.	Description		QTY
1		1	8		6	Α		+1(spare)	16
						В	852 MM	+1(spare)	52
2	<u></u>	1	9		9	С		+1(spare)	52
						D	Bann	3x12mm +1(spare)	72
3		1	10		9	Е	Samonous.	4x30mm +1(spare)	44
						F	\bigcirc		9
4		2	11		9	G	Comm	4x16mm	9
						Н	3 months and	5x50mm	6
5		1	12	0	9	Ι	E DOUGO	4x12mm	2
						J			2
6		2	13		9	K			2
						┙	Statement of the state of the s	4x35mm	2
7	7	2	14		4	М	0		14
						Ν	-annaly	3x16mm	14
			15		3	CL			9
						CR		,	9
						DL			9
						DR	6:		9





YOU MAY NEED (NOT SUPPLIED)





INSTALLATIONS














STEP 6





STEP 7







STEP 9








STEP 11







WALL


WARNING: Anti-tipping hardware is only a deterrent. It is not a substitute for proper adult supervision.

Young children may be injured by tipping furniture and the use of a tipping restraint is highly recommended. This hardware, when properly installed, could provide protection against the unexpected tipping of furniture due to



STEP 13 X9







STEP 14

x9






STEP 15 $\chi 9$





STEP 16 X9



















Thank you very much for purchasing from us.

We have always been trying to provide the best service and reliable products for every customer.

However, accident may happen sometimes, please contact us to resolve any issue before leaving a negative feedback.

Many thanks and welcome to our shop again!

E-mail: uev_eusupport@163.com