






# PARTS LIST



# HARDWARE LIST


NO.	Drawing	Description	Qty	PCS SET	NO.	Drawing	Description	Qty	PCS SET
A		∅15x9	6	PCS	K		∅3x12	2	PCS
B		∅7x35	6	PCS	L		108x25x9MM	2	PCS
C		∅6x30	6	PCS	M		M4x20	4	SET
D		∅3.5x14	2	PCS	N			2	PCS
E			1	SET	O			2	PCS
F		∅4x40	8	PCS	P		∅3.5x16	26	PCS
G		∅35x190	4	PCS	Q		180x20x3	2	PCS
H		4MM	1	PCS	R			4	PCS
I		M6x20	8	PCS	S		∅7.8x38	2	PCS
J			12	PCS					



# 2


## STEP 3

G x4pcs  
H x1pc  
I x8pcs



## STEP 4


J x12pcs



# 3


## STEP 5

E<sub>2</sub> x2pcs  
K x2pcs  
L x2pcs  
M x4pcs




## STEP 6

N x2pcs  
O x2pcs



## STEP 7

P x20pcs




## STEP 8

P x6pcs

Q x2pcs


R x4pcs



# 5

## STEP 9

F x2pcs  
S x2pcs



## STEP 10

