







SRN TR4011T




IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY.

- Please confirm that all components are present before beginning assembly.
- For the protection of your furniture, place all parts on a clean and smooth surface to prevent any damage.
- Please assemble the furniture by 2 persons or more.
- Do not confuse similar screws.
- Do not tighten bolts fully until all parts are connected!
- Please periodically check all fitting and re-tighten as necessary.




Bed Parts are shipped inside a compartment
in the back of the headboard.




PACKING DETAILS: TOTAL 2 BOXES















BOX -1/2



BOX -2/2



BOX -1/2

① x 4 M8 x 20 mm 	② x 6 M8 x 40 mm 	③ x 6 M6 x 35 mm 	④ x 2 M6 x 70 mm 
⑤ x 6 M6 	⑥ x 6 M8 	⑦ x 4 	⑧ x 34 M4 x 16 mm 
⑨ x 40 M4 x 30 mm 	⑩ x 16 M4 x 35 mm 	⑪ x 1 M4 	⑫ x 1 M5 
⑬ x 8 	⑭ x 2 		

Remarks: Extra hardware provided




M6 x 35 mm



M6

③ x 6

⑤ x 6




M6 x 70 mm




④ x 2


⑦ x 4



STEP 1.1



STEP 1.2








M8 x 20 mm

① x 4




STEP 3.1



Do not fully tighten screws before completing step 3.2



STEP 3.2





M8 x 40 mm


② x 6



M8

⑥ x 6







M4 x 30 mm

⑨ x 20

Screwdriver
Not Provided

20x



M4 x 16 mm


⑧ x 2




⑭ x 2


Screwdriver
Not Provided

Optional:


Add stopper at desired side
(Left side or Right side).

2x





M4 x 35 mm

10 x16


M4 x 30 mm

9 x20


M4 x 16 mm

8 x32**13** x8


Fix the cube at the bottom
of 1st, 4th, 7th, and 10th slat.



Step 7.1





Step 7.2





**Screwdriver
Not Provided**

Step 7.3



**TRUNDLE COMPLETED
ASSEMBLY**

Input : AC 100-240V~
50/60Hz 0.3A MAX
Output : 5.0V=2.0A10.0W



COMPLETED
ASSEMBLY