




























Assembly Instruction

①  1pcs	②  1pcs	③  2pcs
④  1pcs	⑤  1pcs	⑥  1pcs
⑦  1pcs	⑧  1pcs	⑨  1pcs
⑩  1pcs	⑪  1pcs	⑫  1pcs
⑬  1pcs	⑭  1pcs	⑮  2pcs
⑯  2pcs	⑰  2pcs	⑱  2pcs
⑲  2pcs	⑳  1pcs	㉑  1pcs
㉒  1pcs	㉓  1pcs	㉔  1pcs
㉕  1pcs	㉖  2pcs	㉗  2pcs
㉘  1pcs	㉙  3pcs	㉚  1pcs
㉛  1pcs	㉜  1pcs	㉝  1pcs
㉞  2pcs	㉟  2pcs	㊱  8pcs
㊲  1pcs	㊳  1pcs	Page 2 of 22


Assembly Instruction

A




M5*40mm 35PCS

B




M6*28mm 37PCS

C




M6*35mm 24PCS

D




M6*35mm 4PCS

E




M4*10mm 5PCS

F




1PCS

G




M6*50mm 6PCS

H




M6 5PCS

I




M4*14mm 24PCS

J




4PCS

K




M6*25mm 4PCS

L



1PCS

M



1PCS

N




M4*18mm 24PCS

O




1.0 8PCS

P




1PCS

Q




1PCS

R




M4 1PCS

S



M6 1PCS

T



M6 1PCS


U



24.2cm

1PCS

V



11cm

1PCS

W



22.2cm

1PCS


X



22.2cm


2PCS

Y



M6*60mm 3PCS

Z




1PCS

a




M8 1PCS




STEP 1

A		M5*40mm	6pcs
---	---	---------	------




STEP 2

A		M5*40mm	5pcs
---	---	---------	------




STEP 3

B		M6*28mm	2pcs
---	---	---------	------




STEP 4

A		M5*40mm	8pcs
---	---	---------	------




STEP 5


A		M5*40mm	6pcs
---	---	---------	------



STEP 6




STEP 7




STEP 8

C		M6*35mm	4pcs
---	---	---------	------




STEP 9




STEP 10

A		M5*40mm	2pcs
B		M6*28mm	8pcs




STEP 11




STEP 12

C		M6*35mm	4pcs
D		M6*35mm	4pcs




STEP 13




STEP 14

B		M6*28mm	8pcs
---	---	---------	------



STEP 15


B		M6*28mm	4pcs
---	---	---------	------



STEP 16

A		M5*40mm	8pcs
C		M6*35mm	4pcs

Attention Pease




The first step is to install N0.A screw.

Second step is to install N0.C screw.

Attention Pease


STEP 17

B		M6*28mm	10pcs
---	---	---------	-------




STEP 18

E		M4*10mm	2pcs
F			1pcs




STEP 19




STEP 20

G		M6*50mm	5pcs
H		M6	5pcs




STEP 21

C		M6*35mm	3pcs
Y		M6*60mm	3pcs




STEP 22

B		M6*28mm	3pcs
I		M4*14mm	8pcs
J			4pcs




STEP 23

E		M4*10mm	3pcs
P			1pcs




STEP 24

B		M6*28mm	2pcs
C		M6*35mm	4pcs




STEP 25

C		M6*35mm	1pcs
G		M6*50mm	1pcs



STEP 26


K		M6*25mm	4pcs
---	---	---------	------




STEP 27

L		1pcs
M		1pcs


Step 1: The light belt first passes through the hole behind the board.



Step 2: Connect the plug
Step 3: Paste led light bar




STEP 28




STEP 29

C		M6*35mm	4pcs
---	---	---------	------




STEP 30




STEP 31

N		M4*18mm	12pcs
---	---	---------	-------




STEP 32

I		M4*14mm	16pcs
0		1.0	8pcs




STEP 33


N	 M4*18mm	12pcs
---	---	-------



STEP 34



STEP 35



STEP 36

This LED light strip
directly into the USB

