











Ax32



Bx32




Cx35



Dx4


STEP 1

 Ax22




STEP 2

 Ax10





STEP 3

	Bx2		Cx2
--	-----	--	-----



STEP 4

	Cx1		Dx2
---	-----	---	-----




STEP 5



Cx2



Dx2




STEP 6



Bx3




Cx3




STEP 7

	Bx2		Cx2
--	-----	--	-----




STEP 8




STEP 9

	Bx10		Cx9
--	------	--	-----




STEP 10


	Bx5		Cx6
---	-----	---	-----



STEP 11



STEP 12



Bx10



Cx10