


ASSEMBLY INSTRUCTIONS


ITEM NO.:N707P392140






















IMPORTANT NOTE:

- ① PLACE ALL PARTS ON A CLEAN AND SMOOTH SURFACE SUCH AS A RUG OR CARPET TO AVOID THE PARTS FROM BEING SCRATCHED.
- ② BEFORE YOU BEGIN, KINDLY FOLLOW THE ASSEMBLY INSTRUCTIONS STEP BY STEP.
- ③ DO NOT TIGHTEN ALL SCREWS AND BOLTS UNTIL THIS ITEM IS FULLY SET-UP.

Detail View



N707P392140

1		2		3		4	
1x		1x		1x		1x	
5		6		7		8	
1x		1x		1x		1x	
9		10		11		12	
1x		1x		1x		1x	
13		14		15		16	
1x		1x		1x		1x	
17		18		19		20	
1x		1x		1x		1x	
21		22		23		24	
1x		1x		1x		2x	
25		26		27		28	
2x		1x		1x		1x	
29		30		31		32	
1x		1x		2x		1x	

33		34		35		36	
	1x		1x		2x		2x
37		38		39		40	
	1x		1x		2x		2x
41		42		43		44	
	2x		1x		1x		2x






Hardware List

A	 Ø 3.5*60 16x	B	 Ø 3.5*40 26x	C	 Ø 3.5*35 2x	D	 Ø 3.0*30 6x
E	 Ø 3.0*28 34x	F	 Ø 3.0*18 6x	G	 Ø 3.0*16 20x	H	 Ø 3.0*10 2x
I	 Ø 6.0*20 24x	J	 Ø 6.0*60 4x	K	 Ø 6.0*55 10x	L	 Ø 6.0*45 6x
M	 Ø 6.0*35 2x	N	 Ø 6.0*16 2x	O	 Ø 6.0*16 2x	P	 Ø 6.0*16 16x
Q	 14x	R	 2x	S	 3x	T	 2x
U	 2x	V	 1x	W	 4x	X	 2x
Y	 4x	Z	 1x	AA	 1x		

ASSEMBLY TOOLS REQUIRED(NOT INCLUDED)



PLEASE BE CAREFUL DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWERTOOLS !




1




J*4
L*2

A*6



Front




2



6.0*60MM

J*4




6.0*45MM

L*2





AA*1

3




3.5*60MM

A*6




B*18
I*24
X*2
Y*4




4

 3.5*40MM	 6.0*20MM	 X*2	 Y*4
B*18	I*24		




5




6

		
AA*1		
 3.5*60MM	 3.5*35MM	 6.0*55MM
A*2	C*2	K*10


M*2




7




E*12




8




A*4
N*2




9



A*4



10



F*6
G*4
R*2
S*2
V*1

S*2	V*1
3.0*18MM	3.0*16MM
F*6	R*2

B*8
G*2
S*1

3.5*40MM	3.0*16MM	S*1
B*8	G*2	




L*4

6.0*45MM	AA*1
L*4	

O*2

O*2

Q*14




15



Q*14

16

E*8




17

3.0*28MM

E*8

18



D*6




3.0*30MM

D*6



G*6




19




G*8
U*2




20




E*6
H*2
T*2




21




E*8



22




W*4
Z*1



23

	
W*4	Z*1



24