




Form A



Form B



B x 20
M15x10mm



C x 20
M6x30mm



D x 5
M4x35mm



E x 1
M4x12mm



F x 9
M3x10mm



G x 1



H x 1
M4x14mm




J x 14
M3x12mm




K x 12




L x 1



M x 1



N x 1



O x 2





P x 12





Q x 1


STEP 1




STEP 2






STEP 3





STEP 4





STEP 5





STEP 6




STEP 7




STEP 8



STEP 9




STEP 10





STEP 11

	C x 4 M6x30mm		D x 4 M4x35mm
---	-------------------------	---	-------------------------




STEP 12

	F x 4 M3x10mm		G x 1
	H x 1 M4x14mm		O x 2



STEP 13

	B x 4 M15x10mm
	C x 4 M6x30mm




STEP 14





J x 12
M3x12mm





K x 12





STEP 15




STEP 16





Form A

 F x 5 M3x10mm	 J x 2 M3x12mm	 M x 1	 N x 1
---	---	---	--



Form B

	F x 5 M3x10mm		J x 2 M3x12mm		M x 1		N x 1
---	-------------------------	---	-------------------------	--	--------------	---	--------------

