





Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.

## STEP 1



STEP 2



## PARTS LIST:


NO.	Description	Sketch	Quantity
1	Back		1PC
2	Seat Cushion		1PC
3	Front Leg		2PCS


## HARDWARE LIST

NO.	Description	Size	Sketch	Quantity			
A	Long Bolt	Ø5/16"x3-1/4"		4PCS			
В	Short Bolt	Ø5/16"x2"	-	7PCS			
С	Flat Washer	Ø5/16"x19mm		11PCS			
D	Spring Washer	Ø5/16"	0	11PCS			
Е	Allen Wrench	5mm		1PC			
F	Straight Allen Key	5mmx100mm		1PC			

NOTE: Straight Allen Key(F) is for use with a power drill.

STEP 3





MADE IN CHINA