






Thank you for purchasing this quality product. Be sure to check all packing material carefully for small parts that may have come loose inside the carton during shipment.


### STEP 1



## STEP 2



### STEP 3









### STEP 4

MADE IN CHINA








TOOLS REQUIRED (NOT PROVIDED)

Screwdriver		1PC
-------------	---	-----

PARTS LIST:

N0.	Description	Sketch	Quantity
1	Back		1PC
2	Seat Cushion		1PC
3	Front Leg		2PCS
4	Front Stretcher		1PC
5	Right Stretcher		1PC
6	Left Stretcher		1PC

## HARDWARE LIST

NO.	Description	Size	Sketch	Quantity
A	Long Bolt	Ø5/16"x3-1/4"		4PCS
B	Short Bolt	Ø5/16"x2"		7PCS
C	Flat Washer	Ø5/16" x19mm		11PCS
D	Spring Washer	Ø5/16"		11PCS
E	Allen Wrench	5mm		1PC
F	Panhead Screw	#8x1-3/4"		6PCS
G	Straight Allen Key	5mmx100mm		1PC

NOTE: Straight Allen Key(G)is for use with a power drill.