


ASSEMBLY INSTRUCTION

PT162/PT164

	PARTS				
1		ТОР	1pc		
2	0	SHELF	1pc		
3		LEG	4pc		


		HARDWARE LIST				
	Α	0	Ø5/16 " * 22	16pcs		
	В	0	Ø5/16 "	16pcs		
	С	(()	Ø5/16 " * 3/4"	16pcs		
	D		5mm	1pc		

STEP 1





STEP 2



Do not tighten screws until completely assemboed