



# LIBERTY FURNITURE

## ASSEMBLY INSTRUCTION

ITEM#: 779/879-T4204/P4204

DESCRIPTION : TRESTLE TABLE TOP/  
TRESTLE TABLE BASE

Thank you for purchasing this quality product. Be sure to check all packing material carefully for small Hardware which may have come loose inside the carton during shipment. Identify and count all Hardware and compare with the Hardware List Below.

PART LIST				
No.	Description	Drawing	Qty.	
①	Table Top with apron		1 Pc	
②	Table Leaf		1 Pc	
③	Top Stretcher		1 Pc	
④	Bottom Stretcher		1 Pc	
⑤	Leg		2 Pcs	

⑥	ASSEMBLY HARDWARE PACK (Pack inside Trestle Table Base)			
No.	Description	Drawing	Size	Qty.
Ⓐ	Hanger Bolt		Ø 5/16" x 89mm	8 Pcs
Ⓑ	Hanger Nut		Ø 5/16"	8 Pcs
Ⓒ	Half Round Washer		Ø 5/16" x 28 x14	8 Pcs
Ⓓ	Wrench		12 mm	1 Pc
Ⓔ	Short Bolt		Ø 5/16" x50mm	8 Pcs
Ⓕ	Long Bolt		Ø 5/16" x 57mm	4 Pcs
Ⓖ	Spring Washer		Ø 5/16"	12 Pcs
Ⓗ	Flat Washer		Ø 5/16" x 19 mm x 2 mm	12 Pcs
Ⓘ	Allen Key		M4	1 Pc



**Liberty Furniture**  
INDUSTRIES, INC.


# LIBERTY FURNITURE

## ASSEMBLY INSTRUCTION


ITEM#: 779/879-T4204/P4204

DESCRIPTION : TRESTLE TABLE TOP/  
TRESTLE TABLE BASE


### STEP 1




### STEP 2




### STEP 3



### STEP 4



### STEP 5



### STEP 6

