## **ASSEMBLY INSTRUCTIONS**

PAGE: 1/5 MODEL: GHSC-1407


### Before you begin, please follow assembly instructions carefully, then follow them step by step.

Read instruction carefully . See Furniture Parts list and Hardware List for guidance . Be sure you have all parts before you start assembling . Place and assemble furniture on a clean flat soft surface, such as carpet or rug to pervent being scratched

PART LIST		QTY
1	TOP PANEL	1 PC
2	BOTTOM PANEL	1 PC
3	SIDE PANEL (L)	1 PC
4	SIDE PANEL (R)	1 PC
5	MIDDLE PANEL	1 PC
6	BACK PANEL	1 PC
7	SHELF PANEL	6 PCS
8	DOOR PANEL (L)	2 PCS
9	DOOR PANEL (R)	2 PCS

SELF-PREPARED TOOLS: Tools below are NOT included in package.				
SCREWDRIVER	HAMMER			
POWER DRILL				

carpet or rug to pervent being scratched.				
HARDWARE				
Α	MINI FIX A1 A2 CCC A3 A3	8 SETS		
В	M8 X 30MM WOOD DOWEL	12 PCS		
С	M6 X 50MM  CSK CAP WOOD SCREW	4 PCS		
D	ALLEN KEY M4	1 PC		
Е	M3.5 X 16MM C.B SCREW	48 PCS		
F	M4 X 25MM C.B SCREW	8 PCS		
G	5/8 NAIL 0	32 PCS		
Н	METAL SHELF SUPPORT	24 PCS		
ı	DRAWER STOPPER(2 PIN)	1 PC		
J	5/8 HINGES	8 PCS		
K	MOOD HANDLE	4 PCS		
L	PVC ROUND LEG	4 PCS		
М	TIPPING PACK  OI M1 M5 M5  M5 M6	2 SETS		






Please ensure that all surfaces and edges with colours/laminations are facing forward/outward.



PAGE: 2/5


## MODEL: GHSC-1407



STEP 2
- Insert hardware A1 onto panel (3), (4) and (5). (Repeat 8 times.)

Insert hardware A2 onto panel (3) and (4).
 (Repeat 4 times.)

- Insert hardware **B** onto panel **(3)**, **(4)** and **(5)**. (Repeat 12 times.)




**SCREWDRIVER** 


REQUIRED

x12


\* Ensure the arrows on hardware A1 point towards mounting positions.



\* In this step hardware A1, A2 and B are pre-inserted.



\* In this step hardware A1, A2 and B are pre-inserted.




### **ASSEMBLY INSTRUCTIONS**

PAGE: 4/5

# MODEL: GHSC-1407

#### STEP 9

- Assemble panel (7) into between panel (3) and (4). (Repeat 6 times.)



\* In this step hardware **H** are pre-inserted.


### STEP 10

- Fix hardware J onto panel (8) and (9) by using hardware E. (Repeat 2 times for each hardware.)



**SCREWDRIVER** 


REQUIRED




(1)

### STEP 11

- Fix hardware K onto panel (8) and (9) by using hardware F.






STEP 12

SCREWDRIVER

REQUIRED

- Fix hardware **J** into panel **(3)** and **(4)** by using hardware **E**. (Repeat 2 times for each hardware.)

position of panel (8) and (9). (Do only when needed.)



\* In this step hardware J have been assembled in panel (8) and (9).

