








## CARE AND MAINTENANCE

Wipe clean with a soft, dry cloth. Test the cleaning method on a hidden area before using them over the entire area.

## NOTICE

- \* Please make sure that you have all parts indicated before you begin assembly of this item.
- \* This item should be assembled on a soft surface to prevent scratching the finished product during assembly.
- \* This item may require periodic tightening.
- \* Do not tighten bolts until completely assembled.

## Part List and Hardware List


PIECE	DESCRIPTION	PICTURE	QUANTITY
A	TABLE TOP		1x
B	H Shaped Leg		1x
C	T Shaped Leg		2x
HW1	Crisscross Metal Plate	 3.0*90*90mm	1x
HW2	Metal Plate	 3.0*25*80mm	4x
HW3	Hex Socket Bolt	 1/4"-20*5/8"	16x
HW4	Allen Key	 M4	1x

# SAFAVIEH

## C O U T U R E

Model# SFV2129

Product Dimensions: 20"D x 22"H




Weight capacity : 25 lbs  
WARNING : DO NOT STAND ON PRODUCT  
WARNING : DO NOT OVER TORQUE BOLTS

## PREPARATION

Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list. If any part is missing or damaged, do not attempt to assemble the product.

Estimated Assembly Time: 20 minutes.

Tools Required for Assembly : Allen Key



### Step 1

Attach 2\*T shaped legs (C) to the inserts of H shaped leg (B), line up Crisscross Metal Plate (HW1) with the assembled legs (B & C), then use Allen Key (HW4) to lock 4\*Hex Socket Bolt (HW3) through Crisscross Metal Plate (HW1) to the assembled legs (B & C).

### Step 2

Line up 4\* Metal Plate (HW2) with the top of each leg, then use Allen Key (HW4) to lock 4\* Hex Socket Bolt (HW3) through the middle hole of the Metal Plate (HW2) to the top of assembled legs (B & C).

### Step 3

Attach the assembled base (B & C) to the bottom of the tabletop (A) and align the 8 holes to be assemble, then use Allen Key (HW4) to lock 8\* Hex Socket Bolt (HW3) through the left and right holes on the Metal Plate (HW2).

### Step 4

Place the table upright and adjust floor glides to level table. Assembly is completed.