







ASSEMBLY INSTRUCTIONS
INSTRUCCIONES


2714S-24 COUNTER HIGH CHAIR
2714S-24 SILLA ALTA DE MOSTRADOR

PARTS LIST
LISTA DE PARTES


1		1PC / PIEZA	A	 Ø1/4" x 20 x 3-1/8" (Chair back leg corner)	4PCS / PIEZAS
2		1PC / PIEZA	B	 Ø1/4" x 20 x 2-3/8" (Chair front leg)	4PCS / PIEZAS
3		2PCS / PIEZAS (L/R)	C	 Ø1/4" x 20 x 1-1/2" (Chair back center)	2PCS / PIEZAS
4		2PCS / PIEZAS	D	 Ø4x38mm	6PCS / PIEZAS
5		1PC / PIEZA	E	 M4 x58mmT	1PC / PIEZA

ASSEMBLY INSTRUCTIONS
INSTRUCCIONES


STEP 1
PASO 1




STEP 2
PASO 2



STEP 3
PASO 3



STEP 4
PASO 4



DO NOT TIGHTEN ALL BOLTS UNTIL COMPLETELY ASSEMBLED.
NO APRETAR LOS TORNILLOS HASTA ARMAR COMPLETAMENTE.