



WF316649
WF316650



ASSEMBLY INSTRUCTIONS



PARTS |

Check that you've received
all parts listed below.


BOX: 1/2
WF316649

② x 1



Side board Left

③ x 1



Side board Right

Hardware




PARTS

Check that you've received
all parts listed below.


BOX: 2/2
WF316650

1 x 1




Head Board

4 x 1



Foot Board

5 x 4



Legs

6 x 10




Slats


HARDWARE


Check that you've received
all hardware listed below.

Hardware List


No.	OUTLOOK	DESC	QTY
(A)		Bolts 5/16"x20 mm	16
(B)		Bolts 5/16"x30 mm	12
(C)		Plain washer Ø19x1.5 mm	28
(D)		Spring washer Ø13x1 mm	28
(E)		Allen key 80x30x4 mm	1
(F)		Screws Ø4x30 mm	20
(G)		Steel Pat	4


STEP 1

A x 4	C x 4	D x 4	E x 1	G x 2
				




STEP 2

A x 4	C x 4	D x 4	E x 1	G x 2
				





STEP 3

B x 6	C x 6	D x 6	E x 1	
				




STEP 4

B x 6	C x 6	D x 6	E x 1	
				




STEP 5

A x 2	C x 2	D x 2	E x 1	
-------	-------	-------	-------	--





STEP 6

A x 2	C x 2	D x 2	E x 1	
-------	-------	-------	-------	--





STEP 7

A x 2	C x 2	D x 2	E x 1	
				





STEP 8

A x 2	C x 2	D x 2	E x 1	
				



STEP 9



STEP 10

