



NO.	LINEDRAWING
A×56	
B×56	
C×16	
D×2	
E×2	
F×20	
G×1	
H×20	
I×6	
J×12	
K×4	





NO.	QTY.
(1)	1
(2)	1
(3)	1
(4)	1
(5)	1
(6)	2
(7)	1
(8)	1
(9)	1
(10)	2
(11)	2
(12)	2
(13)	2
(14)	2
(15)	2
(16)	2
(17)	2
(18)	1
(19)	1

1

H	3.5x14 8x
D	4x

2


H	3.5x14 2x
E	1x
C	Bx40 4x
B	8x
A	8x

**3**


A	4x
B	4x
C	8x40 4x

4

B	4x
A	4x




5




	B
8x	
	A
8x	

6




	I
1x	
	J
6x	
	3x12
12x	

7




	F
3.5x35	
12x	


8




	H 3.5x14
2x	
	E
1x	
	C 8x40
4x	
	B
8x	
	A
8x	

9

A	
B	
4x	4x


10

A	
B	
8x	8x





11

G	
I	
J	


6x 12x

12


D	
8x40	4x
B	
4x	
A	
4x	

13**14****15****16**

17



18



19

