



2*1

1*8
M6*40
+1 (spare)



3*1

4*8
M6
+1 (spare)

