








USER'S MANUAL

KFAB004BK







A	X32+1	B	X4+1	C	X16+1	D	X4+1
							
M6X12mm		M6X35mm		M6X55mm		M6X70mm	

E	X1	F	X8	G	X4
					
M4X55mm		Ø10X50mm		M6XØ38mm	


STEP 1



STEP 2




STEP 3




A	X8	D	X4
			
M6X12mm		M6X70mm	

STEP 4




F	X8
	
Ø10X50mm	

STEP 5



B	X4	C	X16
			
M6X35mm		M6X55mm	

STEP 6



G	X4
	
M6XØ38mm	