



ASSEMBLY INSTRUCTION




























N737P199334







Detail View




PARTS LIST

1  x2	2  x1	3  x1	4  x1
5  x1	6  x2	7  x1	8  x2
9  x2	10  x2	11   x4	12  x4
13  x1	14  x1	16  x1	17  x2
18  x2	19  x6		
20  x2	21  x1	22  x1	23  x1
24  x4	25  x4	26  x1	27  x2
28  x2	29  x1	30  x2	31  x1
32  x2	33  x1	34  x1	35  x1
36  x1	37  x2		


PARTS LIST

A	M6x35  x47	J	φ15 x 11.5  x20
B	M6x15  x8	K	M5x20  x8
C	M6x55  x16	L	M6  x4
D	M6x16  x23	M	M6x40  x20
F	M6x20  x10	N	M6x30  x4
G	 x1	O	M5x15  x2
H	 x4	P	 x1
I	M5x35  x6	Q	M4  x2
S	M6x45  x1	R	 x1
		T	 x1



1



2





3





A M6x35  ×6

4



A M6x35  ×8



5



A | M6x35 |  × 3

F | M6x20 |  × 6



6



D | M6x16 |  × 4

H |  × 4




7



A M6x35  x8

D M6x16  x4

8





A M6x35  x10

L M6  x4

D M6x16  x3



S M6x45  x1

9



I M5x35  x6



10



A M6x35  x2

F M6x20  x4

11





A M6x35  ×8

B M6x15  ×8

D M6x16  ×8



12



A M6x35  ×2




D M6x16  ×2

13




M | M6x40  x20




14




J | $\phi 15 \times 11.5$  x8






15




J | $\phi 15 \times 11.5$  x8





16



J | $\phi 15 \times 11.5$  x4





17



N | M6x30  x4

18



O | M5x15  x2

G |  x1

