



YH1008-T&TXL



Attention: Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other. If the screws are tightened initially, subsequent hole positions may be misaligned.



Hardware arts

- 


M6X35
A 6PCS
- 


M6X45
B 8PCS
- 

M8X45
C 8PCS
- 


4#
D 2PCS


Part list


- 


1 2PCS
- 


2 1PC
- 

3 2PCS
- 

4 2PCS
- 

5 2PCS
- 


6 2PCS
- 

7 1PC
- 

8 10PCS
- 


9 2PCS

Step:1




	M6X45	B	4PCS
	4#	D	1PC

Step:2



	M6X45	B	4PCS
	4#	D	1PC


Step:3



	M8X45	C	8PCS
	4#	D	1PC

Step:4

			
M6X35	A	6PCS	
			
4#	D	1PC	



Step:5

