



# YH1008-K



**Attention: Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other. If the screws are tightened initially, subsequent hole positions may be misaligned.**



Hardware arts

- 

M6X35  
Ⓐ 6PCS
- 

M6X45  
Ⓑ 8PCS
- 


M6X55  
Ⓒ 2PCS
- 


M8X15  
Ⓓ 8PCS
- 


M8X45  
Ⓔ 12PCS
- 


4#  
Ⓕ 2PCS


Part list


- 


① 2PCS
- 


② 1PC
- 

③ 2PCS
- 


④ 2PCS
- 


⑤ 2PCS
- 

⑥ 2PCS
- 

⑦ 1PC
- 



⑧ 10PCS
- 

⑨ 2PCS
- 



⑩ 4PCS
- 

⑪ 2PCS



Step:1



Step:2




### Step:3




Step:4

|                                                                                   |       |   |      |
|-----------------------------------------------------------------------------------|-------|---|------|
|    | M6X35 | A | 6PCS |
|  | 4#    | F | 1PC  |




Step:5

|                                                                                     |       |   |      |
|-------------------------------------------------------------------------------------|-------|---|------|
|    | M8X45 | E | 4PCS |
|  | M8X15 | D | 8PCS |
|  | M6X55 | C | 2PCS |
|  | 4#    | F | 1PC  |



Step:6



Step:7

