



DJYC2426




















ASSEMBLY INTRODUCTION









Exploded View




Plate





Fittings




Step 1




Step 2




Step 3





Step 4






Step 5




Step 6




Step 7




Step 8




Step 9



Step 10




Step 11



C x 4
φ6 x 30 mm


G X4
M5*45

Step 12






A x 12
M6 x 35 mm




Step 13




Step 14




Step 15




Step 16







Step 17




Step 18






Step 19



Step 20




Step 21




E x 16 $\phi 4 \times 12 \text{ mm}$



Step 22



Step 23



Step 24



Step 25

