

















A		M6X15	X68
B		M6X40	X20
C		M6X55	X12
D		M6X65	X30
E		M8X50	X24
F		M6	X4
G		M8	X24
H			X102
J			X53
K			X12
L			X12
M		M6	X2
N		M8	X2
Q			X2
R			X4
Y			X70
X			X4
Z			X4







SPARE PARTS

A		M6X15	X1
B		M6X40	X1
C		M6X55	X1
D		M6X65	X1
E		M8X50	X1
F		M6	X1
G		M8	X1
H			X1
J			X1




1  X4	2  X4
3  X4	4  X8
5  X6	6  X2
7  X2	8  X6
9  X9	10  X42
11  X2	12  X8
13  X2	14  X1


1






D		M6X65	X8
H			X8


2





D		M6X65	X8
H			X8

3



D		M6X65	X8
H			X8


4




X3


A		M6X15	X36
J			X36


5




E		M8X50	X8
G		M8	X8
H			X8

6





E		M8X50	X8
G		M8	X8
H			X8

7






E		M8X50	X8
G		M8	X8
H			X8

8






A		M6X15	X32
H			X32

9






C		M6X55	X10
D		M6X65	X6
H			X6
J			X10

10






B		M6X40	X16
H			X16

11



B		M6X40	X4
C		M6X55	X2
F		M6	X4
J			X6

12






14

J			X1
---	---	--	----

13



1



Q		X2
R		X4
X		X4
Z		X4

14

2



K		X12
L		X12
Y		X70

3

