






① ASSEMBLY INSTRUCTION

MODEL NO.HC5788




Components/QTY	Components/QTY	Components/QTY
① 1PC	② 1PC	③ 1PC
		

STEP 1




STEP 2




② ASSEMBLY INSTRUCTION

MODEL NO.HC5788


STEP 3




STEP 4



STEP 5




STEP 6



STEP 7

⚠ Note : The seat cushions have been vacuum packed for transportation purposes. After unpacking, please allow up to 72 hours so that they can return to their original shape.



STEP 8

