



D2006RT-WHITE


HARDWARE LIST

PARTS LIST


| CARTON | NO. | SKETCH | DESCRIPTION | QTY |
|--------|-----|--------|-------------------------|--------|
| 2-2 | 1 | 9 | Bolt (1/4" x 1-1/4") | 12 PCS |
| | 2 | 9 | Bolt (1/4" x 1-3/4") | 3 PCS |
| | 3 | 9 | Bolt (1/4" x 3/4") | 3 PCS |
| | 4 | 0 | Spring Washer (1/4") | 15 PCS |
| | 5 | 0 | Washer (1/4") | 15 PCS |
| | 6 | | Allen Wrench (4mm) | 1 PC |

| CARTON | NO. | SKETCH | DESCRIPTION | QTY |
|--------|-----|--------|-------------|-------|
| 2-1 | Α | | Table top | 1 PC |
| 2-2 | В | | Pedestal | 3 PCS |
| | С | | Top Ring | 1 PC |
| | D | | Base Ring | 1 PC |


Step 1




Note: At this stage, do not fully tighten the bolts .




D2006RT-WHITE






D2006RT-WHITE





Note: At this stage, do not fully tighten the bolts .

Step 5




Note: At this stage, do not fully tighten the bolts .






D2006RT-WHITE








D2009DC-WHITE D2009DC-BLACK

HARDWARE LIST


| NO. | SKETCH | DESCRIPTION | QTY |
|-----|--------|---------------------|-------|
| 1 | 97 | Bolt(1/4"x2-1/8") | 2 PCS |
| 2 | 97 | Bolt(1/4"x1-1/2") | 4 PCS |
| 3 | 0 | Spring washer(1/4") | 6 PCS |
| 4 | 0 | Washer(1/4") | 6 PCS |
| 5 | | Allen wrench(4mm) | 1 PC |

PARTS LIST

| NO. | SKETCH | DESCRIPTION | QTY |
|-----|--------|-------------|------|
| А | | Seat | 1 PC |
| В | | Back leg | 1 PC |
| С | | Front leg | 1 PC |



Step 2



Note: Do not fully tighten the bolts at this step.

Note: Do not fully tighten the bolts at this step.

