

ASSEMBLY INSTRUCTIONS


ITEM NO.:N769P282380B



















IMPORTANT NOTE:

- ① PLACE ALL PARTS ON A CLEAN AND SMOOTH SURFACE SUCH AS A RUG OR CARPET TO AVOID THE PARTS FROM BEING SCRATCHED.
- ② BEFORE YOU BEGIN,KINDLY FOLLOW THE ASSEMBLY INSTRUCTIONS STEP BY STEP.
- ③ DO NOT TIGHTEN ALL SCREWS AND BOLTS UNTIL THIS ITEM IS FULLY SET-UP.

Detail View




N769P282380B

1		2		3		4	
1pc		1pc		1pc		1pc	
5		6		7		8	
1pc		1pc		1pc		1pc	
9		10		11		12	
1pc		1pc		1pc		1pc	
13		14		15		16	
4pcs		2pcs		2pcs		2pcs	
17		18		19		20	
1pc		1pc		2pcs		1pc	
21		22		23		24	
1pc		1pc		3pcs		1pc	
25		26		27		28	
1pc		2pcs		2pcs		6pcs	
29		30		31		32	
3pcs		3pcs		1pc		1pc	

33	34
	
1pc	3pcs

Hardware List

A	 Ø 3.5*60 4pcs	B	 Ø 3.5*45 23pcs	C	 Ø 3.5*40 12pcs	D	 Ø 3.0*30 20pcs
E	 Ø 3.0*28 64pcs	F	 Ø 3.0*25 6pcs	G	 Ø 3.0*22 4pcs	H	 Ø 3.0*16 4pcs
I	 Ø 3.0*12 5pcs	J	 Ø 3.0*16 4pcs	K	 28pcs	L	 1pc
M	 2pcs	N	 3pcs	O	 5pcs	P	 8pcs
Q	 4pcs	R	 4pcs				

ASSEMBLY TOOLS REQUIRED(NOT INCLUDED)





PLEASE BE CAREFUL DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWERTOOLS !

Step 1

K*8

Step 2

K*8

Step 3

K*12

Step 4

L*1

M*2

Step 5

I*5

O*5

Step 6

E*8

E*4

F*2

G*2

Step 7

E*4	F*2	G*2

E*4

F*2

G*2

Step 8

E*4	F*2	G*2

B*2

Step 9

B*2

C*4

Step 10

C*4

B*2


Step 11

B*2

B*7

Step 12


B*7



Step 13




B*6



Step 14




C*8




Step 15



P*8




Step 16



Step 17



J*4




Step 18



B*2




D*18




Step 19

E*24	N*3




Step 20

E*12




Step 21

E*12




Step 22

B*4	D*2



Step 23

A*4



Step 24

F*2	H*4	Q*4



R*4