






Parts BOX1 N761P280055




1 x 1




2 x 1




3 x 1




7 x 2




8 x 2




9 x 1



10 x 1



12 x 2



15 x 2

Parts BOX2 N761P280056




4 x 1



5 x 1



6 x 1



13 x 2



16 x 2




17 x 2




18 x 1

Hardware




A

M8*20
34PCS



B

M8*40
23PCS




C

M8*60
10PCS




D

1 PC




11 x 2





14 x 6


Step 1






B M8*40 4PCS




Step 2




B M8*40 9PCS





Step 3

 **B** M8*40 6PCS  **C** M8*60 2PCS



Step 4


 **A** M8*20 12PCS



Step 5




A M8*20 14PCS



Step 6




A M8*20 8PCS




Step 7



B M8*40 4PCS






Step 8




Step 9



M8*60 8PCS



finish



ASSEMBLY INSTRUCTION

N761P280055

N761P280056

