



ASSEMBLY INSTRUCTION


Combination 1




Combination 2




Hardware List




① X2




② X2




③ X6




④ X2



⑤ X2




⑥ X2




⑦ X16+1


Ø8*30mm



⑧ X16+1



⑨ X16+1




⑩ X2




⑪ X4

Ø3*15mm



⑫ X24+2




⑬ X32+3



⑭ X32+3


Ø3*19mm



⑮ X1




⑯ X2



Ⓐ X2




Ⓑ X4



Ⓒ X2


Ø8*3/4"




Ⓓ X2

Ø8*1-1/2"


Ⓔ X2




Step 1 :




Step 2 :



Step 3 :




Step 4 :




Step 5 :

X2




Step 6 :


X2




Step 7 :




Step 8 :



Step 9 :





WALL



X2

Step 10 :



Step 11 :

WALL

