















JFL-W7200

Version:1.1



HARDWARE LIST


A  6×35mm 8 PCS	B  8 PCS	C  6×30mm 44(+2)PCS	D  8×30mm 3 PCS	E  M3.5×14mm 8 PCS
F  M5×40mm 24(+2) PCS	G  28(+2) PCS	H  2 PCS	J  M6×30mm 22(+1) PCS	

PANEL LIST

1  2PCS	2  2PCS	3  2PCS	4  1PC
5  2PCS	6  2PCS	7  2PCS	8  2PCS
9  4PCS			


Installation method of three
in one rod and buckle






01

INSTALLATION STEPS


Ax8 

02

Bx8 
Cx12 


03

Gx28 




04

Cx16 
Fx16 




05



Cx16 
Fx8 


06



Jx4 

07

Dx3



08

Ex8



Hx2

