




ASSEMBLY INSTRUCTION




First, place Part A on the ground, then place Part B on Part A and align it with the threaded holes. Screw Bolt F and Washer E into the threaded holes.



Then, place Part C on the side of Parts A and B, and screw Bolt F and Washer E into the threaded holes on the side. Repeat the same procedure for the other side.



After erecting the assembled components, screw the last four bolts F with washers E into the threaded holes behind A.



Completion Diagram