




AssemblyInstructions





Exploded view




Exploded view



Exploded view



Component diagram



Hardware List


X110



(A)

32mm

X110



(B)

ø12*10mm

X56



(C)

ø6*30mm


X34



(D)

ø5*12mm


X16



(E)

ø3*12mm


X4



(F)

38*17mm


X4



(G)

42*17mm

X8



(J)

M4*18mm


X4



(K)

125*12*20mm


X8



(P)

ø4*20mm


X56



(M)

ø3*16mm




X56




(L)

12*10*12mm

Hardware List






X1  (N)	X5  (a) ø4*30mm/大帽
X8  (b) ø4*15mm	X5  (c) ø12*12mm
X1  (d) N*20*3mm	X4  (e) 118*20*18mm

Installation steps:1





(A)  [X10] (B)  [X16] (C)  [X12] (D)  [X8]

Installation steps:2




Installation steps:3




B  [X6]

Installation steps:4





A [X16]

Installation steps:5




- (B) [X16] (C) [X16] (D) [X24] (P) [X4]


Installation steps:6



Installation steps:7





Installation steps:8





(A) [X24] (B) [X40]

Installation steps:9







A [X28]


Installation steps: 10




Installation steps: 11







Installation steps:12





Installation steps: 13




Installation steps: 14




Installation steps:15



Installation steps: 16



Installation steps: 17



a



[X5]

d




[X1]

c



[X5]

Installation steps: 18




(b)








[X8]

(e)



[X4]

Installation steps: 19



L




[X56]

M



[X56]

N



[X1]