
























N704P379112D&N704P379112E


Assembly Instruction






A  93PCS	B  93PCS	C  M3.5*15mm 82PCS	D  M6*40mm 4PCS
E  M6*15mm 4PCS	F  M4*18mm 4PCS	G  16PCS	H  4PCS
I  2PCS	J  2PCS	K  2PCS	L  1PC
M  2PCS	N  2PCS	O  4PCS	P  2PCS
Q  2PCS	R  2PCS	S  2PCS	T  2PCS
U  1PC			

STEP 1




	Ax8
	Bx8

STEP 2




	Ax14
	Bx14

STEP 3




	Dx4
---	-----

STEP 4




	Cx8
	Ox2

STEP 5




	Ax6
	Bx6

STEP 6




	Ax6
	Bx6

STEP 7




	Ax4
	Bx4
	Cx4
	Ix2

STEP 8




	Ax15
	Bx13
	Gx6


STEP 9



STEP 10




STEP 11




	Ax16
	Gx10

STEP 12




	Bx16
---	------

STEP 15




	Cx2
	Lx1

STEP 16




	Ex4
	Qx2
	Rx2

STEP 17




	Cx6
	Lx1

STEP 18




	Hx4
	Cx8

STEP 19




	Cx8
---	-----

STEP 20




	Cx12
	Jx2
	Nx2

STEP 21



	Cx8
	Kx2

STEP 22



	Cx2
	Sx2
	Tx2