



A x1




B x1




C x4

D x4



E x4



F x1



G x10



H x1



J x8



N x4



O x1



M6x10mm

a x16



M6x35mm

b x16



d x28




e x16




f x1


1




2




3




4




5




6




7




9




8




10



11



12



13

