













Assembly Instruction






Parts List(EN)




Parts List(EN)

1  x1	2  x1	3  x1
4  x1	5  x2	6  x2
7  x1	8  x3	9  x10
10  x1	11  x2	12  x1

A  M6*12MM x26	B  M6*30MM x17	C  S=4MM x1
---	---	--

Assembly Steps(EN)


STEP 1




A		x8
C		x1

Assembly Steps(EN)

STEP 2




STEP 3




Assembly Steps(EN)

STEP 4




STEP 5




Assembly Steps(EN)

STEP 6




STEP 7



Assembly Steps(EN)


STEP 8




B  x3

C  x1

STEP 9





B  x8

C  x1

Assembly Steps(EN)

STEP 10



B		x4
C		x1